

qb robotics®




qb SoftHand
INDUSTRY

QUICK-START GUIDE



EE_H_IND_R_24V_231_100



G-DCWHI2.5/100EES

4 x



EN ISO 10642 M6x10

1 x



EN ISO 8734 A d6x10 h6

1 x



MC_TOOL_ALLENKEY_M_4



EC_CBL_UTP_6_RJ45_BLK_050




EC_CBL_22_02_L50_RR_200




EC_CBL_26_CRMP3_WIRE_050




EC_CBL_26_M8FA8_CRIMP_100










EC_CBL_26_CRMP24_WIRE_050



G-DCWHI2.5/100EES



#	instructions		
A			
B			
C			

#	instructions		
D			
E			
F			
G	